

Carvinghinweise

Carvingschienen sind hohen Belastungen ausgesetzt, da sie eine schmale Spitze ohne Umlenkstern haben. Deshalb ist es besonders wichtig, auf eine ausreichende Kettenschmierung und eine lockere Kettenspannung zu achten. Die Kette sollte im gespannten Zustand von alleine leicht durchhängen, so dass unten die Hälfte der Treibglieder rausschaut.

Les guides carving sont mis à rude épreuve en raison du faible rayon de la tête du guide-chaîne ne possédant pas de roue d'entraînement. Il convient donc impérativement de veiller au bon graissage de votre chaîne et de tendre un peu moins fortement la chaîne. La moitié de l'ergot des maillons d'entraînement devrait être visible sur la face inférieure du guide.

Please notice, that the chain tension should be reduced slightly when Carving guide bars are used. In such cases half the drive links should be visible on the underside of the bar. This has to do with the very narrow bar nose radius and the very high loads that occur there if chain tension is too high. Therefore, it is particularly important to provide a sufficient chain lubrication.

